

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water

1562 W. FIRST AVENUE
Columbus, Ohio (12)

No. 185251

County Mont Township Randolph Section of Township 26
Owner John Walker Address Conington Pike Dayton
Location of property see below

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 44'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 20 G.P.M. Duration of test _____ hrs.
Drawdown 1 ft. Date May 30, 1917
Developed capacity _____
Static level—depth to water 37' ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	2 Ft.
Top Soil		
Clay	2	21
W/O/sand + gravel	21	22
Till	22	37
W/O/sand + gravel	37	42
Blue Shale	42	70
Water at 42'		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Curtis C. Conway
Address 7944 Harington Ave
Dayton, Ohio

Date May 30, 1917
Signed Curtis C. Conway