

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 186072

County Franklin Township Warren Section of Township _____
Owner Clyde Wiener Address 1027 Risher Road Warren Ohio
Location of property _____

CONSTRUCTION DETAILS


BAILING OR PUMPING TEST

Casing diameter 5 Length of casing 52 Pumping rate 7 G.P.M. Duration of test 2 hrs.
Type of screen _____ Length of screen _____ Drawdown _____ ft. Date _____
Type of pump _____ Developed capacity _____
Capacity of pump _____ Static level—depth to water 30 ft.
Depth of pump setting _____ Pump installed by _____
Date of completion _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Y. Clay</u>	0 Feet	<u>30</u> Ft.
<u>B. s.s.</u>	<u>30</u>	<u>52</u>
<u>B. shale</u>	<u>52</u>	<u>120'</u>



See reverse side for instructions

Drilling Firm Clyde G. Grier
Address Rt #3 Eastland D

Date Nov 17 1958
Signed Clyde G. Grier