

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 186092

County Franklin Township Champion Section of Township _____
Owner Stromp Bros Address 4224 Snahoning Ave
Location of property Stromp Allotment

CONSTRUCTION DETAILS

Casing diameter 7' 5 1/8" Length of casing 58'
Type of screen _____ Length of screen _____
Type of pump Plunger Submersible
Capacity of pump _____
Depth of pump setting 100'
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 60 G.P.M. Duration of test 6 hrs.
Drawdown _____ ft. Date April 15/60
Developed capacity _____
Static level—depth to water _____ ft.
Pump installed by Culver

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Yellow Clay</u>	<u>0 Feet</u>	<u>14' Ft.</u>
<u>Blue clay</u>	<u>14</u>	<u>28'</u>
<u>Blue Shale</u>	<u>28</u>	<u>58'</u>
<u>White sand</u>	<u>58'</u>	<u>90'</u>
<u>Blue shale</u>	<u>90</u>	<u>110</u>
<u>White sand</u>	<u>110</u>	<u>125'</u>
<u>Blue shale</u>	<u>125</u>	<u>135'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Clyde A. Culver Sr
Address Rt 3 Corta IO

Date May 2 1960
Signed Clyde A. Culver Sr