

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

29
No. 186331

County Licking Township Lima Section of Township —

Owner George Schwartz Address LOT #40 BELMAR ST. SUMMIT RIDGE HTS.

Location of property 500' N. - STATE RT #16 & 1/4 mile E. OF FRANKLIN - LICKING COUNTY LINE

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 131'
Type of screen 3/16 holes Length of screen 42"
Type of pump not purchased
Capacity of pump at time of
Depth of pump setting well completion
Date of completion —

BAILING OR PUMPING TEST


Pumping rate 15 G.P.M. Duration of test 3 hrs.
Drawdown 15 ft. Date 10-4-58
Developed capacity 15 G.P.M.
Static level—depth to water 65 ft.
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top Soil</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>(Brown) Clay</u>	<u>2'</u>	<u>10'</u>
<u>Clay & Gravel</u>	<u>10'</u>	<u>128'</u>
<u>Gravel</u>	<u>128'</u>	<u>131'</u>
<u>Water @ 128 - 131 in gravel</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Swingle Drilling
Address Box #1 Alexandria, O.

Date 10-27-58
Signed R. T. Swingle



M304