

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 189233

County Pickaway Township Madison Section of Township _____
Owner J. L. McKee Address _____
Location of property Perrill Road & County Line Road.

CONSTRUCTION DETAILS


BAILING OR PUMPING TEST

Casing diameter 6 Length of casing 15- Pumping rate _____ G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____ Drawdown 2- ft. Date Sept 5-8
Type of pump _____ Developed capacity 500- Per. Hr. 8-
Capacity of pump _____ Static level—depth to water _____ ft.
Depth of pump setting _____ Pump installed by OWNER
Date of completion _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	<u>6</u> Ft.
<u>Yel. Clay</u>	<u>6</u>	<u>15</u>
<u>Gray</u>	<u>15-</u>	<u>29</u>
<u>Gray Stone</u>	<u>29</u>	<u>50</u>
<u>Gray Shale</u>		



See reverse side for instructions

Drilling Firm P.H. Goodwin
Address 2005 E. Livingston

Date 9-5-8
Signed P.H. Goodwin

40