

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

W65
No. 190737

County Licking Township Etna Section of Township _____
Owner Glen Whitman Address Patospala
Location of property Route 40 1/2 mile W of Route 99 motel

CONSTRUCTION DETAILS

Casing diameter 3 Length of casing 86-6
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown 80 ft. Date April 30 -57
Developed capacity 600
Static level—depth to water 56 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Clay</u>		<u>30</u>
<u>Clay sand</u>	<u>30</u>	<u>45</u>
<u>mushy sand</u>	<u>45</u>	<u>50</u>
<u>Clay</u>	<u>50</u>	<u>81-6</u>
<u>sand</u>	<u>81-6</u>	<u>86-6</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Walter Davis & Son Date April 30 -57
Address Baltimore Md Signed Walter Davis

LOCATED

65