

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 192569

County Madison Township Pleasant Section of Township.....
Owner Daniel Day Address RT. 1 - Mt. Sterling
Location of property Burr Oak Addition, Mt. Sterling

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 96'
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion.....

BAILING OR PUMPING TEST


Pumping rate 12 G.P.M. Duration of test 2 hrs.
Drawdown 10 ft. Date May 3, 1958
Developed capacity.....
Static level—depth to water 40' ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	11 Ft.
Clay	11	13
Sand	13	96
Clay & sand	96	108
Limestone		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Sumner Well Drilling Date May 5, 1958
Address 142 Lida Ave. Shelby, Ohio Signed [Signature]

SECOND SC.

A2