

X-2196,400

WELL LOG AND DRILLING REPORT

ORIGINAL

Y=614,800 N

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 195270

County Cuyahoga Township Parma Section of Township S.E.
Owner Bob Martin Address 7940 Grace Ave. Cleve. O.
Location of property 500' N of Spruce Rd on W 130th St.

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 21'
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion.....

BAILING OR PUMPING TEST

Pumping rate 5 G.P.M. Duration of test 1 hrs.
Drawdown — ft. Date 12-28-56
Developed capacity.....
Static level—depth to water 60 ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Br. Clay + Gravel</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>Gray " + "</u>	<u>12</u>	<u>18</u>
<u>Gray Shale</u>	<u>18</u>	<u>139</u>
<u>Berea Cap</u>	<u>139</u>	<u>141</u>
<u>Berea Sandstone</u>	<u>141</u>	<u>180</u>


water @ 177'

03013330

706 01142311

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Wershing + Mack
Address Valley City, O.

Date 12-29-56
Signed R.E. Mack