

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 192571

423

County Franklin Township Madison Section of Township _____
Owner Don S. Sauer Address Waterford Rd. Canal Winchester
Location of property on Sander Rd. 1/4 mile south of Lawrence Rd. Pike

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 40'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 15 ft. Date June 11, 1958
Developed capacity _____
Static level—depth to water 5 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	0 Feet	<u>32 Ft.</u>
<u>Sand + Gravel</u>	<u>32</u>	<u>40</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Sumner Well DrillingDate June 11, 1958Address 142 Lisle Ave. P.O. Box 500Signed Don S. Sauer