

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 198884

County Crawford Township Whetstone Section of Township 7
Owner John Livingston Address Buysman
Location of property _____

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 87'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping rate 3 G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity 3 gpm
Static level—depth to water 30 ft.
Pump installed by _____

WELL LOG

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

87 Ft.

Clay
shale

87

99


Sulphur water

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Sec 7 Whetstone Twp



W.

E.

S.

See reverse side for instructions

Drilling Firm G. R. Huchey & Son
Address Buysman

Date July 25, 1957
Signed G. Huchey

73
LOCATED

13