

LOG AND DRILLING REPORT

ORIGINAL

375

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 202176

County Franklin Township Mt. Zion Section of Township _____

Owner Jack Dawson Address _____

Location of property 2696 York Rd

LOCATED

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST


Casing diameter 5' Length of casing 41' Pumping rate 20 G.P.M. Duration of test 1 hrs.
Type of screen perforated Length of screen 5" Drawdown None ft. Date Oct. 25, 1958
Type of pump 1 1/2 HP Jet Developed capacity 20 g.p.m.
Capacity of pump 360 g.p.h. Static level—depth to water 11 ft.
Depth of pump setting 35 Pump installed by Fred W. Hayes
Date of completion Nov. 2, 1958

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Soil</u>	<u>0</u>	<u>7</u>
<u>Clay</u>	<u>7</u>	<u>38</u>
<u>course sand</u> <u>& gravel</u>	<u>38</u>	<u>41</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Hayes Well Drilling Date Nov. 2, 1958

Address 2774 Goshens town Rd Signed Fred W. Hayes

238