

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 202322

County Franklin Township Warren Section of Township _____
Owner J. B. Nelson Address 1255 Baker St. Warren Ohio
Location of property South side of Baker St. 400' east of State Rt. 45 So. 1st Ave

CONSTRUCTION DETAILS

Casing diameter 5 1/8 Length of casing 92'
Type of screen _____ Length of screen _____
Type of pump Hand pump
Capacity of pump 30'
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 6 G.P.M. Duration of test 4 hrs.
Drawdown _____ ft. Date Aug. 24 1958
Developed capacity 6
Static level—depth to water 15 ft.
Pump installed by Don Culver Co.

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
<u>clay</u>		<u>46</u>
<u>sand. mud.</u>	<u>46</u>	<u>85</u>
<u>water. 92'</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Don Culver Co.
Address 4994 Mahoning Ave
Warren Ohio

Date Aug. 24 1958
Signed Don Culver