

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 203731

County Merger Township Butler Section of Township Section 13
Owner Ray Gilman Address Celina Ohio, Butler Co
Location of property 2 1/2 Miles South of Celina O. on St Paul

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 55'
Type of screen 1/2" Length of screen 55'
Type of pump 1/2 HP Submerged Pump
Capacity of pump 350 Gal. Per Hour
Depth of pump setting 55' ft
Date of completion 8/10/64

BAILING OR PUMPING TEST


Pumping rate 30 G.P.M. Duration of test 3 hrs.
Drawdown 10 ft. Date 8/10/64
Developed capacity 800 Gal. Per Hour
Static level—depth to water 21 ft.
Pump installed by R.M. Andrew P#5
Celina Ohio

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>yellow clay</u>	<u>0 Feet</u>	<u>25' Ft.</u>
<u>Blue clay</u>	<u>25'</u>	<u>55'</u>
<u>limestone</u>	<u>55'</u>	<u>84'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm R.M. Andrew
Address P#5 Box 139 Celina, Ohio.

Date 8/8/64
Signed R.M. Andrew

LOCATED
61