

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 203745

County Merger Township Jefferson Section of Township Jefferson
Owner McKelland, Yancy Address R# Celina Ohio
Location of property 1/2 mi west of Celina on S.P. 29 = 1 mile south on 118
1/2 mi west on north side of Road

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 35'
Type of screen Yane Length of screen
Type of pump Hand
Capacity of pump 50 Gal per hour
Depth of pump setting 40'
Date of completion 6/26/67

BAILING OR PUMPING TEST


Pumping rate 30 G.P.M. Duration of test 9 hrs.
Drawdown 8 ft. Date 6/26/67
Developed capacity 50 Gal per hour
Static level—depth to water 16' ft.
Pump installed by R. M. Andrews
Celina Ohio

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>of Clay</u>	<u>0 Feet</u>	<u>15' Ft.</u>
<u>Don't find</u>	<u>15'</u>	<u>25'</u>
<u>Plum Clay</u>	<u>25'</u>	<u>35'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm R. M. Andrews
Address R# 5 R# 129 Celina Ohio

Date 6/27/67
Signed R. M. Andrews

57
LOCATED