

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 204297

County Green Township Benjamin Section of Township.....
Owner Eddie Fairchild Address
Location of property 1884 Turnbull Lot 48 Krollwood Acres

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter <u>5 7/8</u> Length of casing <u>39</u>	Pumping rate..... G.P.M. Duration of test..... hrs.
Type of screen..... Length of screen.....	Drawdown <u>2</u> ft. Date <u>Aug 19, 1957</u>
Type of pump.....	Developed capacity <u>10.5 GPM</u>
Capacity of pump.....	Static level—depth to water <u>6</u> ft.
Depth of pump setting.....	Pump installed by.....
Date of completion.....	

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads; etc.
	0 Feet	Ft.	N.
Clay	39		W. E.
			Turnbull Temp Rd.
			(15) "6"