

WELL LOG AND DRILLING REPORT

State of Ohio
 DEPARTMENT OF NATURAL RESOURCES
 Division of Water
 1500 Dublin Road
 Columbus, Ohio

RESCUED

21

No. 207069

County Pike Township Union Section of TownshipOwner Wm. W. Bowers Address Bowers OhioLocation of property 9 1/2 miles S.W. of Stockdale Ohio

CONSTRUCTION DETAILS

Casing diameter 5 1/2" Length of casing 41.3'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping rate G.P.M. Duration of test hrs.

Drawdown ft. Date

Developed capacity

Static level—depth to water 10' ft.

Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	18 Ft.
Shale hard	18	45
Water at	23	

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W.

E.

S.

See reverse side for instructions

Drilling Firm Herbert B. BowersDate Sept 26 1961