

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 207866

County SHELBY Township SALEN Section of Township _____
Owner CLINTON N. JENNINGS Address PORT JEFFERSON
Location of property LANE ST 2 STS NORTH OF ROUTE 47

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing _____
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 2 G.P.M. Duration of test 1/2 hrs.
Drawdown 1 ft. Date MAR 9
Developed capacity 120
Static level—depth to water 4 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>RED CLAY</u>	<u>0 Feet</u>	<u>2 Ft.</u>
<u>GRAVEL</u>	<u>8</u>	<u>37 1/2</u>
<u>WATER</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm _____

Address DEERAZZODate MAR 9 1966Signed E. S. ZimmermanMASON Rd