

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 209270

County Medina Township Lafayette Section of Township LOT 139 TRACT 1
Owner Wesley White Address 5312 LAKE RD MEDINA O.
Location of property 1/2 mi NORTH OF ST RT # 42 ON CO RD # 19.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 27
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 9/24/69

BAILING OR PUMPING TEST


Pumping rate 4 G.P.M. Bailor Test Duration of test 3 hrs.
Drawdown 59 ft. Date _____
Developed capacity _____
Static level—depth to water 12 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>BR CLAY</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>BI "</u>	<u>12</u>	<u>27</u>
<u>SHALE</u>	<u>27</u>	<u>59</u>
<u>WATER AT 53</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm _____
Address Medina O.

Date 10/22/69
Signed [Signature]

LOCATED

134