

WE LOG AND DRILLING REPOI

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

146
No. 209273

County Medina Township Sharon Section of Township LOT #5
Owner John Strojali Address 5356 Ridge Rd. Wadsworth OH
Location of property 1/4 mi South of ST RT #18 on ST RT #94

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 35'
Type of screen.....Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion Nov 2 1968

BAILING OR PUMPING TEST

~~BAILOR TEST~~
Pumping rate 5 G.P.M. Duration of test.....hrs.
Drawdown.....ft. Date.....
Developed capacity.....
Static level—depth to water 24 ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	9 Ft.
BR CLAY	9	20
BLUE MUD		
SOFT SANDY SHALE	20	35
BIG INJUN SAND	35	84
WATER AT 84		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

