

WELL LOG AND DRILLING REPORT

State of Ohio
 DEPARTMENT OF NATURAL RESOURCES
 Division of Water
 1500 Dublin Road
 Columbus, Ohio

(50)
 No. 209276

County Medina Township Montville Section of Township Lot # 40
 Owner Mike Harms Address 4312 Poe Rd.
 Location of property 1 mile east of ST RT #3 on Co R #71

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 106'
 Type of screen..... Length of screen.....
 Type of pump.....
 Capacity of pump.....
 Depth of pump setting.....
 Date of completion 5/26/70

BAILING OR PUMPING TEST


Bailer Test
 Pumping rate 6 G.P.M. Duration of test 5 hrs.
 Drawdown..... ft. Date.....
 Developed capacity.....
 Static level—depth to water 40 ft.
 Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>BR CLAY</u>	<u>0 Feet</u>	<u>19 Ft.</u>
<u>BI "</u>	<u>19</u>	<u>63</u>
<u>BR Mud (Sharon)</u>	<u>63</u>	<u>106</u>
<u>Big INJUN SAND</u>	<u>106</u>	<u>110</u>
<u>WATER AT 108</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
 State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm.....
 Address Medina O.

Date 5/26/70
 Signed K E C

LOCATED
 65