

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 209277

County Medina Township Lafayette Section of Township _____
Owner Kim Walker Address 7148 CHATHAM RD.
Location of property 3/4 mile West of ST RT # 42 on ST RT # 162

CONSTRUCTION DETAILS

Casing diameter 5 Length of casing 39' 6"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 10/6/70

BAILING OR PUMPING TEST

Bailer Test
Pumping rate _____ G.P.M. Duration of test 3 hrs.
Drawdown _____ ft. Date _____
Developed capacity 15 G.P.M.
Static level—depth to water 70 ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

12 Ft.

12

20

20

30

30

39


39

105

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

E.



See reverse side for instructions

Drilling Firm _____

Date 10/13/70Address Medina Co.Signed C. E. Cole

LOCATED