

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

~~HE~~ 295
No. 210129

County FRANKLIN Township PERRY Section of Township _____

Owner ROBERT PETTIT Address 2988 BROOKDOWN DR.
WORTHINGTON, O. R.F.D.#2

Location of property SAME (Brookside Estates)

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 1/2 Length of casing 84'
Type of screen None Length of screen None
Type of pump Rapiddayton 1/2 H.P. Submersible
Capacity of pump Model #52D47 885 G.P.H.
Depth of pump setting 95'
Date of completion 14th July 1959

Pumping rate 8 G.P.M. Duration of test 24 hrs.
Drawdown 90' ft. Date 14th July 1959
Developed capacity 8 G.P.M.
Static level—depth to water 50' ft.
Pump installed by AAA Pump Sales & Service
Dublin, O. TU 91355

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
Yellow Clay	0 Feet	55 Ft.
Fine Sand	55	60
Blue Clay	60	82
Shale	82	100

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Grenvale

Pl.

Brookdown

Drive

W.

Granville Rd.

Route 161

E.

Well Location:
4' South Of South Outside Wall
Where Discharge Pipe Goes Through
Crawl Space, 3' Bury

Village Of Lin-
worth Approx. 1 M
~~1/2 M~~

S.

See reverse side for instructions

Drilling Firm Sells-Suburban Well & Water Sup Date 14th July 1959

Address Dublin, Ohio TU 91355 Signed Robert L. Sells

354