

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

(33)

No. 212710

County Butler Township Milford Section of Township 23
Owner Hugh Ryle Address P.O. Collinsville, Ohio
Location of property Old Huston Rd Lot 17 Collinsville

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST


Casing diameter 4 1/4 Length of casing 42 ft Pumping rate 5 G.P.M. Duration of test 2 hrs.
Type of screen None Length of screen — Drawdown None ft. Date 10-2-61
Type of pump — Developed capacity 300 gal. hr.
Capacity of pump — Static level—depth to water 15' ft.
Depth of pump setting — Pump installed by —
Date of completion 10-2-61

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>gravel</u>	0 Feet	<u>15</u> Ft.
<u>clay - sand</u>	<u>15</u>	<u>25</u>
<u>sand</u>	<u>25</u>	<u>35</u>
<u>sand & gravel</u>	<u>35</u>	<u>42</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Faggart Pump Repair & Well Drilling Date 10-6-61
903 Bonerville Jacksonburg Rd.
Address Collinsville, Ohio Signed Stewart H. Faggart

(27)