

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 212711

County Butler Township Milford Section of Township 23

Owner Hugh Ryle Address P.O. Collinsville, Ohio

Location of property Left on Old 127 off of Depot Rd. in Collinsville

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 43 1/2 ft. Pumping rate 5 G.P.M. Duration of test 2 hrs.
Type of screen None Length of screen — Drawdown None ft. Date 10-9-61
Type of pump — Developed capacity 300 gal. hr.
Capacity of pump — Static level—depth to water 15' ft.
Depth of pump setting — Pump installed by —
Date of completion —


BAILING OR PUMPING TEST

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Top soil</u>	<u>0 Feet</u>	<u>4' Ft.</u>
<u>Gravel sand</u>	<u>4'</u>	<u>20'</u>
<u>sand</u>	<u>20'</u>	<u>28'</u>
<u>clay</u>	<u>28'</u>	<u>35'</u>
<u>sand & gravel</u>	<u>35'</u>	<u>42'</u>
<u>sand & gravel</u>	<u>42'</u>	<u>43 1/2'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Fazzart Pump Repair & Well Drilling Date 10-9-61
903 Bloomerville Jacksonburg Rd.
Address Saneriville, Ohio Signed Stewart H. Fazzart

(28)