

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 212713

County Butler Township H. Clair Section of Township 15
Owner Mrs. Follie Galbard Address Indian Rock Beach Florida
Location of property 2110 Caldwell St. Williamsdale Hamilton, Ohio

CONSTRUCTION DETAILS

Casing diameter 4 1/4" Length of casing 43'
Type of screen None Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion 11-4-61

BAILING OR PUMPING TEST


Pumping rate 5 G.P.M. Duration of test 2 hrs.
Drawdown None ft. Date 11-4-61
Developed capacity 300 gal. P.H.
Static level—depth to water 21' ft.
Pump installed by —

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Gravel & Sand</u>	0 Feet	<u>25'</u> Ft.
<u>clay</u>	<u>25'</u>	<u>35'</u>
<u>Sand</u>	<u>35'</u>	<u>38'</u>
<u>clay</u>	<u>38'</u>	<u>40'</u>
<u>Gravel</u>	<u>40'</u>	<u>43'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Taggart Pump Repair & Well Drilling Date 11-4-61
Address 703 Bonerville Dr. Cincinnati, Ohio Signed Stewart H. Taggart

