

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 214177

County Walworth Township Carpfield Section of Township _____
Owner George Stalle Address 7789 Miles Ashtabula Rd
Location of property Spring Lake Dr Warren O

CONSTRUCTION DETAILS

Casing diameter 7 D.D. Length of casing 122
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump None
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 20 G.P.M. Duration of test _____ hrs.
Drawdown 50 ft. Date Oct 10 1958
Developed capacity 30+
Static level—depth to water 30 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	35 Ft.
Clay sand gravel	35	105
Dark clay	105	116
Sand gravel	116	130
Gray sand	130	136
" Shale		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm E. J. LynchDate Oct 10 1958Address Marshall Ridge

Signed _____

(245)