

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 214198

County 9 Mahoning Township Austintown Section of Township
Owner Armand / Oak Address 4478 Mahoning Ave
Location of property Lanternway Rd Greenstown 90

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 20
Type of screen Length of screen
Type of pump jet
Capacity of pump 6 G.P.M.
Depth of pump setting 60
Date of completion

BAILING OR PUMPING TEST


Pumping rate 20 G.P.M. Duration of test 1 hrs.
Drawdown 0 ft. Date
Developed capacity 20
Static level—depth to water 30 ft.
Pump installed by E. J. Lynch

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	9 Ft.
Yellow sand rock	9	30
White " "	30	71

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm

Address

Date

Signed

LOCATED

80