

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 214200

County Washington Township Amherst Section of Township JACKSON
Owner LeRoy Gessner Address 194 W. Glenaven
Location of property Lipke Rd Youngstown, O

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 21
Type of screen Length of screen
Type of pump Submersible
Capacity of pump 8 GPM
Depth of pump setting 80 ft
Date of completion

BAILING OR PUMPING TEST

Pumping rate 20 G.P.M. Duration of test 1 hrs.
Drawdown ft. Date
Developed capacity 20
Static level—depth to water 18 ft.
Pump installed by E. J. Lynch


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	9 Ft.
Clay	9	32
Blue shale	32	39
Gray sand	39	55
Light shale	55	61
Gray sand	61	79
Dark shale	79	95
Light sand	95	112
" shale		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N. Elev. of Rock: 935



See reverse side for instructions

Drilling Firm E. J. LynchDate Sept 18 1959Address Universal Ridge

Signed

82
LOCATED
82