

WELL LOG AND DRILLING REPORT

ORIGINAL

97

State of Ohio
DEPARTMENT OF NATURAL RESOURCES

Division of Water
1500 Dublin Road
Columbus, Ohio

BELONGS IN

SEC. 25, SYLVANIA TWP

No. 214679

County LUCAS Township RICHFIELD Section of Township 25

Owner SPUYTEN DUYVAL GOLF CLUB Address SYLVANIA OHIO

Location of property 1/10 mile W. of CRISSEY RD. ON U.S. 20 - ST. 120
CENTRAL AVE

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 29

Type of screen NONE Length of screen -

Type of pump NONE

Capacity of pump -

Depth of pump setting -

Date of completion 11-9-60

BAILING OR PUMPING TEST

Pumping rate 2 G.P.M. Duration of test 2 hrs.

Drawdown 40 ft. Date 11-9-60

Developed capacity 3 G.P.M.

Static level—depth to water 14 ft.

Pump installed by NONE

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	Ft.
<u>Sand</u>	<u>0</u>	<u>9</u>
<u>Clay</u>	<u>9</u>	<u>21</u>
<u>Clay-Gravel</u>	<u>21</u>	<u>26</u>
<u>Sand</u>	<u>26</u>	<u>28</u>
<u>Shale Brack</u>	<u>28</u>	<u>52</u>
<u>Shale Gray</u>	<u>52</u>	<u>56</u>
<u>Shale Black</u>	<u>56</u>	<u>66</u>
<u>Shale Gray</u>	<u>66</u>	<u>70</u>
<u>Shale Black</u>	<u>70</u>	<u>71</u>

water 66

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. U.S. 20 - ST 120 E.

CRISSEY RD. S.
GOLF CLUB

See reverse side for instructions

670
SL

Drilling Firm Ors Smith

Date 11-12-69