

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 217133

County Allen Township Shawnee Section of Township Sec 23
Owner Barnett Grimmer Address Lima 3 south gate
Location of property 2 1/2 S 1/2 W Lima south gate 4207

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 1/8 Length of casing 195 Pumping rate 20 G.P.M. Duration of test..... hrs.
Type of screen..... Length of screen..... Drawdown 13 ft. Date.....
Type of pump..... Developed capacity.....
Capacity of pump..... Static level—depth to water 44 ft.
Depth of pump setting..... Pump installed by.....
Date of completion.....

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay


From

To

From	To
0 Feet	<u>40</u> Ft.
<u>40</u>	<u>60</u>
<u>60</u>	<u>90</u>
<u>90</u>	<u>160</u>
<u>160</u>	<u>170</u>
<u>170</u>	<u>190</u>
<u>190</u>	<u>195</u>
<u>195</u>	<u>199</u>
<u>199</u>	<u>237</u>

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

clay
Sand
clay
mucky sand
clay
Sand
clay
sand
lime rock



See reverse side for instructions

Drilling Firm Barnett GrimmerDate Sept 26 - 1961Address 561 E. LivingstonSigned Barnett GrimmerAlberia

LOCATED