

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 217291

County Belmont Township Warren Section of Township 3
Owner Raymond Rott Address Barnesville R.R. 3
Location of property 3/4 mi east of Rt 147 on Sandy Ridge

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 6 1/4 Length of casing 21 Pumping rate 4 G.P.M. Duration of test 10 hrs.
Type of screen Length of screen Drawdown ft. Date May 23, 1960
Type of pump Developed capacity
Capacity of pump Static level—depth to water 60 ft.
Depth of pump setting Pump installed by owner
Date of completion


WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To
Top soil	0 Feet	5 Ft.
yellow sand	5	50
gray shale	50	70
Blue shale	70	85
dark shale	85	100
Water at 60 ft		

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.



S.

See reverse side for instructions

Drilling Firm Glen E. Warrick Date May 23, 1960
Address 507 N. Lingle Ave
Barnesville, OH Signed Glen E. Warrick