

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 217470

County Knox Township Milford Section of Township _____
Owner Ronnie Styers Address R. 5. Mt. Vernon, Ohio
Location of property 5 Mi. N. of 5 corners on E. side of Co. Rd. 19

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 66
Type of screen None Length of screen _____
Type of pump Deep Well
Capacity of pump 180 G.P.H.
Depth of pump setting 58
Date of completion 4/29/62

BAILING OR PUMPING TEST

Pumping rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 18 ft. Date 4/29/62
Developed capacity 10 G.P.M.
Static level—depth to water 35 ft.
Pump installed by H.M. Hellwig


WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
clay, yellow	0 Feet	10 Ft.
clay, blue	10	30
Sand	30	38
clay, blue	38	65
clay, yellow	65	66
Sand	66	67

Water at 66 ft.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm H.M. Hellwig & Sons
Address Rt. 1, Letice, Ohio

Date 5/15/62
Signed H.M. Hellwig