

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 217471

County Knox Township Pleasant Section of Township _____

Owner Charles R. McPherson Address R. 3, Mt. Vernon, Ohio

Location of property 2 1/2 Mi. E of Mt. Vernon on twp. Rd. 262

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 41'
Type of screen None Length of screen _____
Type of pump Hand
Capacity of pump _____
Depth of pump setting _____
Date of completion 6/24/62

BAILING OR PUMPING TEST


Pumping rate 10 G.P.M. Duration of test 2 hrs.
Drawdown 2 ft. Date 6/24/62
Developed capacity 10 G.P.M.
Static level—depth to water 23' ft.
Pump installed by Owner

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Gravelly clay	0 Feet	21 Ft.
Blue clay Hard pan	21	23
Sand	23	35
Hard pan yellow	35	38
Sand	38	41

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm H.M. Hellwig & Sons Date 7/22/62

Address R. 1, Utica, Ohio Signed H.M. Hellwig