

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 219779

County Stark Township Can. Plain Section of Township 14

Owner L. H. Dieringer Address 4727 Linden Ave. N.E. Canton

Location of property 5581 Middlebranch Rd. Canton, Ohio

CONSTRUCTION DETAILS

Casing diameter 4 in. Length of casing 42 ft.
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown 10 ft. Date _____
Developed capacity 12 gal per min
Static level—depth to water 25 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
sand and gravel	0 Feet	20 Ft.
blue clay	20	37
shale	37	52

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Paul Rhoades

Date _____

Address Canton, Ohio

Signed _____