

## WELL LOG AND DRILLING REPORT

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
1500 Dublin Road  
Columbus, Ohio

No. 222223

County KNOX Township MILFORD Section of Township SOUTHOwner G. A. MORELAND Address RT. #2 Centerburg OhioLocation of property On County Road #

## CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 57  
Type of screen NONE Length of screen  
Type of pump  
Capacity of pump  
Depth of pump setting  
Date of completion 7.3.63

## BAILING OR PUMPING TEST


Pumping rate 20 G.P.M. Duration of test 3 hrs.  
Drawdown NONE ft. Date 7.3.63  
Developed capacity 20 G.P.M.  
Static level—depth to water 34 ft.  
Pump installed by OWNER

## WELL LOG

| Formations<br>Sandstone, shale, limestone,<br>gravel and clay | From          | To            |
|---------------------------------------------------------------|---------------|---------------|
| <u>YELLOW CLAY</u>                                            | <u>0 Feet</u> | <u>20 Ft.</u> |
| <u>BLUE CLAY</u>                                              | <u>20</u>     | <u>30</u>     |
| <u>SAND</u>                                                   | <u>30</u>     | <u>33</u>     |
| <u>CLAY &amp; GRAVEL</u>                                      | <u>33</u>     | <u>55</u>     |
| <u>SAND, GRAVEL, WATER</u>                                    | <u>55</u>     | <u>57</u>     |

## SKETCH SHOWING LOCATION

Locate in reference to numbered  
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm C & H DRILLING CO.Address JohnstownDate 7.4.63Signed K. F. Porter

LOCATED

8