

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 223061

County Mahoning Township Green Section of Township Sec 23
Owner Donald Howl Address Greenford
Location of property Sec 23

CONSTRUCTION DETAILS

Casing diameter 5-3/8 Length of casing 14
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity _____
Static level—depth to water 5-1 ft.
Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
Clay		14
Sand Stone	14	27
Shale Gray	27	59
Black	59	88
Coal	88	89
Clay	89	97
Shale Gray	97	125

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Pine Lake

S.

See reverse side for instructions

Drilling Firm Ross Latta
Address East Palestine

Date Oct 13 - 1958
Signed Ross Latta

LOCATED