

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1500 Dublin Road
Columbus, Ohio

No. 224744

County Portage ~~Lamar~~ Township Lugfield Section of Township

Owner Charles Morris Address 2077 Martin Rd.

Location of property 4081 ETTER RD.

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 73

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping rate 6 G.P.M. Duration of test 1/4 hrs.

Drawdown — ft. Date 6.6.66

Developed capacity

Static level—depth to water 19' ft.


Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Fill on top soil</u>	<u>0 Feet</u>	<u>12 Ft.</u>
<u>clay & gravel</u>	<u>12</u>	<u>21</u>
<u>" " & sand</u>	<u>21</u>	<u>39</u>
<u>gray clay</u>	<u>39</u>	<u>51</u>
<u>" " & gravel sand.</u>	<u>51</u>	<u>60</u>
<u>gray clay grav "</u>	<u>60</u>	<u>70</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm Snyder Drilling

Address 915 H. and S.

Phone 6 01

Date 6-6-66

Signed Leroy L. Snyder

LOCATED
148