

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

83
Change
No. 227499

County DELAWARE Township BERLIN Section of Township _____
Owner Cecil David Address Delaware O.
Location of property Cheshire Rd

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 23'6"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date 9/5
Developed capacity _____
Static level—depth to water 10 ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From 0 Feet	To Ft.
<u>yellow clay</u>	<u>0</u>	<u>20</u>
<u>Slate</u>	<u>20</u>	<u>58</u>
<u>Gray shale</u>	<u>58</u>	<u>63</u>
<u>Brown</u>	<u>63</u>	<u>135</u>
<u>Brown</u>	<u>135</u>	<u>155</u>
<u>Blue limestone</u>	<u>155</u>	<u>164</u>


947
30
927

947
133 1/2
81 1/2

get. Chem. Anal.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Glen Sherman
Address 609 Rock St Marion O
Phone 2-4423

Date SEPT. 5, 1959
Signed Glen Sherman

