

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 228250

County Franklin Township Mifflin Section of Township _____
 Owner P.R. Hay Address 4177 Westerville Rd.
 Location of property Same.

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 112
 Type of screen - Length of screen -
 Type of pump Submersible
 Capacity of pump 129 PM
 Depth of pump setting 90 feet
 Date of completion Feb 20, 1964

BAILING OR PUMPING TEST

Pumping rate 15 G.P.M. Duration of test 3 hrs.
 Drawdown 0 ft. Date Feb 19
 Developed capacity Same
 Static level—depth to water 68 ft.
 Pump installed by Lehman Drilling

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Clay	0 Feet	28 Ft.
muddy sand & Gravel	28'	98'
Dry Sand	98	108
Gravel	108	112

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.
 Morse Rd.
 well
 W. 1/4 mile
 South of
 Morse Rd.
 E.
 Westerville Rd.
 S.

See reverse side for instructions

Drilling Firm Lehman Drilling
 Address 606 Riverview Dr.

Date March 15, 1964
 Signed James Lehman