

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

15290 LVA17

No. 231692

County KNOX Township Morris Section of Township _____
 Owner Earl Morris Address Fredericktown, O. R.F.D. 1-43019
 Location of property 2 mi. S + E Fredericktown, O. on Co Highway 6, E 200 ft.

CONSTRUCTION DETAILS

Casing diameter 4 Length of casing 50
 Type of screen _____ Length of screen _____
 Type of pump _____
 Capacity of pump _____
 Depth of pump setting _____
 Date of completion _____

BAILING OR PUMPING TEST


Pumping rate 30 G.P.M. Duration of test 1 hrs.
 Drawdown 2 ft. Date 11-9-66
 Developed capacity _____
 Static level—depth to water 12 ft.
 Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	8 Ft.
Clay		
Clay + gravel	8	22
sand	22	29
Clay + gravel	29	42
gray sand stone rock	42	44
Clay + gravel	44	46
gray sand stone rock	46	48
Clay + gravel	48	50
& sand stone rock	50	65

Water at 61

SKETCH SHOWING LOCATION



See reverse side for instructions

Drilling Firm Clyde Edwards
 Address Fredericktown, O. R.F.D. 3
43019

Date 11-9-66
 Signed Clyde R. Edwards