

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohiow14
No. 232574

County Licking Township McKean Section of Township.....
 Owner Frank Colville Address Utica, Ohio
 Location of property 1 mile East from intersection 661 and 16 city road

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 80'
 Type of screen..... Length of screen.....
 Type of pump..... 1 h. sub.
 Capacity of pump..... 15 gals. min.
 Depth of pump setting..... 120'
 Date of completion..... March 13, 1961

BAILING OR PUMPING TEST


Pumping rate 18 G.P.M. Duration of test 1 hrs.
 Drawdown..... 15 ft. Date March 13, 1961
 Developed capacity..... 24
 Static level—depth to water..... 80' ft.
 Pump installed by..... E. J. Snedden

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>Clay</u>	0 Feet	<u>70</u> Ft.
<u>Shale</u>	<u>70'</u>	<u>80'</u>
<u>Rock</u>	<u>80'</u>	<u>120'</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm E. J. Snedden
 Address 138 Miller Street

Date April 13, 1961
 Signed E. J. Snedden

14