

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 235250

County Medina Township Liverpool Section of Township S.Owner Dillard Lester Address _____Location of property CH 112 - 100 ft W. of CH 56

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 33-7
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test _____ hrs.
Drawdown _____ ft. Date _____
Developed capacity _____
Static level—depth to water _____ ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	_____ Ft.
<u>yellow clay</u>		<u>12</u>
<u>blue "</u>	<u>12</u>	<u>20</u>
<u>stony "</u>	<u>20</u>	<u>30</u>
<u>blue "</u>	<u>30</u>	<u>40</u>
<u>shelly "</u>	<u>40</u>	<u>50</u>
<u>gray shale</u>	<u>50</u>	<u>55</u>

water came in 50-55
good supply, slightly salty.

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

See reverse side for instructions

Drilling Firm Luke FitzsimmonsAddress Valley City, O.Date June 11, 1961Signed Mrs. L. FitzsimmonsLOCATED
62