

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 235811

County Preble Township Horison Section of Township 25

Owner J. B. Connor Address Rt 1 Leesburg, Ohio

Location of property Northeast side of Rt 40 - 200 ft East of Rd. Side Park 1 1/4 Mi. East of Leesburg

CONSTRUCTION DETAILS

Casing diameter 6" O.D. Length of casing 41'-6"
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump 1.0 g.p.m.
Depth of pump setting 60 ft.
Date of completion.....

BAILING OR PUMPING TEST

Pumping rate 30 G.P.M. Duration of test 1 1/2 hrs.
Drawdown 1 ft. Date 9/10/59
Developed capacity 2.0 g.p.m.
Static level—depth to water 34 ft.
Pump installed by H. McCullough

WELL LOG


Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>clay</u>	0 Feet	<u>1'-8" Ft.</u>
<u>sandy clay</u>	18	22
<u>clay</u>	22	36
<u>sandstone</u>	36	55
<u>limestone</u>	55	70

Water at 50'-62'

County 50

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Robert McCullough
Address Phillipsburg, Ohio

Date 9/10/59
Signed