

WELL LOG AND DRILLING REPORT

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

¹³²
No. 238342

County Geauga Township Chester Section of Township W

Owner William Stute Address Cleveland 24 Ohio

Location of property Corner Cedar Crest Trail & Birdland Trail 5/4164

CONSTRUCTION DETAILS

Casing diameter 5 7/8 Length of casing 20
Type of screen Length of screen
Type of pump Goulds 3/4 hp. Submersible
Capacity of pump 12 g.p.m.
Depth of pump setting 115'
Date of completion

BAILING OR PUMPING TEST


Pumping rate 12 G.P.M. Duration of test 2 hrs.
Drawdown 5 ft. Date
Developed capacity
Static level—depth to water 90 ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	2.3 Ft.
<u>Clay</u>		
<u>Shale</u>	<u>23</u>	<u>105</u>
<u>Sandstone</u>	<u>105</u>	<u>130</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



S.
See reverse side for instructions

Drilling Firm Fredelburgh Well Drilling Date January 1960
Address Newbury, Ohio Signed Daniel L. Fredelburgh