

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 239061

County Hocking Township Falls Section 69
 Owner Albert Schirley Address Logan, Ohio, R. 4
 Location of property On Ohio Rt. 1/4 mile East of State Rt. 76

CONSTRUCTION DETAILS

Casing diameter 4 1/2 in Length of casing 75.9"
 Type of screen None Length of screen None
 Type of pump _____
 Capacity of pump _____
 Depth of pump setting _____
 Date of completion July 13/1963

BAILING OR PUMPING TEST


Pumping rate 800 G.P.M. Duration of test 1 hrs.
 Drawdown 8" ft. Date 7/13/63
 Developed capacity 800 gal per hr
 Static level—depth to water 30" ft.
 Pump installed by Dunn

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	9 Ft.
<u>6' clay</u>	<u>9</u>	<u>37</u>
<u>Blue clay</u>	<u>37</u>	<u>44</u>
<u>Hard shale Rock</u>	<u>44</u>	<u>50</u>
<u>Soft Blue shale</u>	<u>50</u>	<u>53</u>
<u>Hard Blue shale</u>	<u>53</u>	<u>60</u>
<u>Hard sand Rock</u>	<u>60</u>	<u>70</u>
<u>Soft white sand</u>	<u>70</u>	<u>85</u>
<u>Rock</u>		
<u>Big Ingun sand</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions