

WELL LOG AND DRILLING REPORT

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 242486

County Summit Township Springfield Section of Township _____
Owner A. J. DePrato Address 1943 Canby Rd. Akron 12, O.
Location of property 2081 Manor Dr.

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 65'0"
Type of screen 3'0" - Bronze Length of screen 3'0"
Type of pump Drop Type
NO 15
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

Pumping rate..... G.P.M. Duration of test..... 2 hrs.
 Drawdown..... 40 ft. Date..... Dec 8, 1960
 Developed capacity..... 5 G.P.M.
 Static level—depth to water..... 20' Top of Pipe ft.
 Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Sand & Gravel	0 Feet	28 Ft.
Blue clay	28	50
Blue Clay & Sand	50	60
Sand	60	65

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

W. E.

Killion Rd.

Mann Dr.

3 1/2 Mi.

1/2 Mi.

Squaw Co.

Stark Co.

S.

See reverse side for instructions

Drilling Firm H.V. Yanti's
Address 972 S. Munroe Rd
Tallmadge Ohio

Date Dec, 10, 1960
Signed H Verne Vantre