

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 242487

County Portage Township Suffield Section of Township _____
Owner G. Saylor Address 2492 Palm Rd. Suffield Ohio

Location of property _____

CONSTRUCTION DETAILS

Casing diameter 4" Length of casing 12' 7"
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST


Pumping rate _____ G.P.M. Duration of test 1/2 hrs.
Drawdown 5 ft. Date Dec. 16, 1960
Developed capacity 15 G.P.M.
Static level—depth to water 14' ft.
Pump installed by _____

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
Yellow Clay + Stones	0 Feet	11 Ft.
Broken Yellow Sandstone	11	16
Yellow Sandstone	16	24
White sandstone	24	30
Yellow Sand stone	30	37
Water lower Yellow Sandstone		

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm H.V. Yantis
Address 972 S. Munroe Rd
Tallmadge Ohio

Date Dec. 16, 1960
Signed H. Verne Yantis

