

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 243586

County Pike Township Jackson Section of Township 22

Owner Lawrence Campbell Address R. 2 East 0

Location of property 1 Farm South Campbelltown on E side Rd

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 160 Ft
Type of screen..... Length of screen.....
Type of pump.....
Capacity of pump.....
Depth of pump setting.....
Date of completion.....

BAILING OR PUMPING TEST


Pumping rate 12 G.P.M. Duration of test..... hrs.
Drawdown 35 ft. Date.....
Developed capacity 12
Static level—depth to water 50 ft.
Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
YC	0 Feet	18 Ft.
BC	18	80
Sand	80	82
B/C	82	155
Sand	155	156
YC	156	160
Rock	160	170

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Flory & Payton

Date 6-19-66

Address

Signed J. A. Flory