

WELL LOG AND DRILLING REPORT

ORIGINAL

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 243596

County Preble Township Jackson Section of Township 18 16

Owner Robert Shaper Address R-2 Eaton

Location of property 3 house - left side North of RR in Comphestown

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 107

Type of screen..... Length of screen.....

Type of pump.....

Capacity of pump.....

Depth of pump setting.....

Date of completion.....

BAILING OR PUMPING TEST

Pumping rate 14 G.P.M. Duration of test..... hrs.

Drawdown 25 ft. Date.....

Developed capacity 14 GPM

Static level—depth to water 40 ft.


Pump installed by.....

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
<u>ac/well</u>	0 Feet	<u>32</u> Ft.
<u>BC</u>	<u>32</u>	<u>90</u>
<u>YC</u>	<u>90</u>	<u>97</u>
<u>BC</u>	<u>97</u>	<u>107</u>
<u>Rock</u>	<u>107</u>	<u>117</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



See reverse side for instructions

Drilling Firm Glory & Patton

Address R-3

Date Eaton Ohio 12-30-67

Signed Arthur J. Long