

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio

729

PLEASE USE PENCIL
OR TYPEWRITER.
DO NOT USE INK.

DEPARTMENT OF NATURAL RESOURCES

Division of Water
1562 W. First Avenue
Columbus, Ohio

No. 243890

County Franklin Township Blair Section of TownshipOwner Mr. Dean Porto Address 755 Stelzer Rd.Location of property 7250 Morse Road

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 39Type of screen no Length of screenType of pump no

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST

Pumping rate G.P.M. Duration of test hrs.

Drawdown 5 ft. Date July 1 - 1963Developed capacity 16 GPMStatic level—depth to water 12 ft.

Pump installed by

WELL LOG

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

39 Ft.393942Clay
FreestoneSandstone

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

7250 Morse Rd

W.

3 miles

E.

MorseRoute 62

S.

See reverse side for instructions

Drilling Firm Walter ShumakerAddress Powell, OhioDate July 1, 1963Signed Walter Shumaker

757